



Foam-Less Liquid Defoamer



High pressure cleaning equipment and residue from past cleaning often combine to create foam in your waste tank. Foam can cause loss of vacuum pressure and ruin your equipment. Foam-Less in your waste tank suppresses foam to keep your equipment running at peak efficiency.

Instructions

Shake well before use. Concentrate - add 1 to 2 oz. directly into waste tank before cleaning and after dumping tank. Increase or decrease amount depending on foaming conditions created by water flow, previous residue and/or size of tank.

Dilution - 1 part to 16 parts of water when pouring or spraying in vacuum hose periodically during cleaning. Increase or decrease dilution of product depending on foaming conditions created by water flow, previous residue, auto pump outs and/or size of tank.



RTU pH 7

Available in gallon bottles and 4 x 1 gallon cases

Part # CH47GL

Hydro-Force | 4282 South 590 West Salt Lake City, UT 84123

www.hydroforce.com • (800)-948-1779

See Material Safety Data Sheet at www.hydroforce.com/msds for safety and regulatory information.